Map ID MAP FINDINGS

Direction Distance

Distance EDR ID Number
Elevation Site EDR ID Number
EDR ID Number

A5 AUTO GARAGE NY Spills S102402172 SSW 1109 NEPTUNE AVE N/A

**AUTO GARAGE** 

< 1/8 0.041 mi.

0 ft.

218 ft. Site 4 of 23 in cluster A

BROOKLYN, NY

Relative: SPILLS: Higher Name: Address:

 Address:
 1109 NEPTUNE AVE

 City,State,Zip:
 BROOKLYN, NY

 Spill Number/Closed Date:
 9608899 / 2004-02-03

 Facility ID:
 9608899

 Facility Type:
 ER

 DER Facility ID:
 246218

 Site ID:
 304821

 DEC Region:
 2

 Spill Cause:
 Deliberate

Spill Cause: Deliberate Spill Class: C3 2401 SWIS: Spill Date: 1996-10-17 Investigator: **MCTIBBE** Referred To: Not reported 1996-10-17 Reported to Dept: CID: 252

Water Affected: CONEY ISLAND CREEK

Spill Source: Gasoline Station or other PBS Facility

Spill Notifier: Local Agency
Cleanup Ceased: Not reported

Cleanup Meets Std: False
Last Inspection: Not reported

Recommended Penalty: False UST Trust: False Remediation Phase: 0

Date Entered In Computer: 1996-10-17
Spill Record Last Update: 2004-02-03
Spiller Name: UNKNOWN
Spiller Company: AUTO GARAGE
Spiller Address: 1109 NEPTUNE AVE

Spiller Company: 001
Contact Name: UNKNOWN

DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

TIBBE handled by nycdep."

Remarks: "citizens complained of dumping of waste motor oil which is ending up

in the water way"

All Materials:

Site ID: 304821 Operable Unit ID: 1037008 Operable Unit: 01 Material ID: 344631 Material Code: 0015 Material Name: motor oil Case No.: Not reported Material FA: Petroleum Quantity: .00 Units: G .00 Recovered:

Oxygenate: Not reported